

TIG Welder

<b>Facility:</b>	<b>Written By:</b>	<b>Approved By:</b>	<b>Date Created:</b>	<b>Date of Last Revision</b>

<b>Hazards Present:</b>	<b>PPE or Devices Required:</b>	<b>Additional Training Required:</b>
Explosion	Eye protection	WHMIS
Sparks	Welding hoot with beanie	Welding Gas Usage
Burns	Steel toed boots	
noise	Welding apron, jacket, gloves	
Eye injury		

**Safe Work Procedure:**

- 1) Close light curtain at entrance to welding booth to protect shop personnel from momentary exposure to arc
- 2) Activate ventilation hood or sing arm fume extractor for type of welding being done
- 3) Put on required PPE
- 4) Turn Argon Compressed Gas Cylinder Regulator on
- 5) Turn welder on with master wall switch at switch on/off
- 6) Prior to welding, metal parts are treated with Phosphoric Acid in paint booth
- 7) Weld metal
- 8) Welded joint is finished with hand held grinder
- 9) Gas and electrical is operated by an unguarded foot switch
- 10) TIG system has closed loop cooling system
- 11) Return power switch to off position.

***If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure***

**REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR**

<p><b>Guidance Documents/Standards:</b></p> <p>MB Workplace Safety &amp; Health Act &amp; Regulations:</p> <p>Part 6 Personal Protective Equipment Part 17 Welding and Allied Processes</p>	<p>This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years</p>
	<p>Reviewed By WSH Committee:</p> <p>Date:</p>