

Quick Cut Saw Inspection

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Eye injuries	Steel toed boots	Flag person training
Hand injuries	Eye protection	
Airborne particles	Hand protection	
Noise pollution	Hearing protection	
	Hard hat	

Safe Work Procedure:

- 1) Check On/Off switch is functioning properly
- 2) Check rip cord for frays
- 3) Check air filter
- 4) Check gas levels
- 5) Check spark plug
- 6) Ensure guards are in place and secure
- 7) Check cutting blades
- 8) Do check cut ensuring to cut away from body

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

<p>Guidance Documents/Standards:</p> <p>MB Workplace Safety & Health Act & Regulations:</p> <p>4 General Workplace Requirements</p> <p>5 First Aid</p> <p>6 Personal Protective Equipment</p> <p>16 Machines, Tools and Robots</p> <p>16.15 Miscellaneous Machines and Tools</p>	<p>This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years</p>
	<p>Reviewed By WSH Committee:</p> <p>Date:</p>