## Change/Replace Screens

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Fall from heights	Steel toed boots	
Hand/Limb Injuries	Eye protection	
Pinch points	Hand protection	
	Hard Hat	
	Fall Suppression	
	Scaffold/Elevated Work Platform	

## Safe Work Procedure:

- 1) Screens must be free and clear of dirt and rocks
- 2) Power plant must be LOCKED OUT and powered off
- 3) Wash circuit engine must be LOCKED OUT and powered off
- 4) Remove large nuts, washers and springs from sides
- 5) Remove tensioned bolts from the screens (typically 16 pieces)
- 6) Remove the long tensioner plates (typically 4 ft. and 8 pieces)
- 7) Remove the screen sections through delivery plate at the ends of the screens
- 8) Remove se the above steps for the installation process
- 9) All nuts should be tightened 3 full turns from snug
- 10) Do not try to adjust any of the cables suspending the screen within the carriage assembly

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

## REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:  MB Workplace Safety & Health Act &	This Safe Work Procedure will be reviewed any time the task, equipment or materials
Regulations:	change and at a minimum of every three
5 First Aid	years
6 PPE 15 Confined Spaces	Reviewed By WSH Committee:
22.5 Powered Mobile Equipment	
28 Scaffold & Other Elevated Work Platforms	Date: