Floor Jack

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Requi	red: Additional Training Required:		
Slip/Trip	Steel toed boots			
Fall Injury	Eye protection			
Airborne Particles	Hand protection			
Vehicle Malfunction				
Eye Injury				
	Safe Work Proc	edure:		
1) Inspect surrounding work as				
 Inspect surrounding work area, clean machine and remove any clutter Check jack for visible signs of wear and proper lubrication 				
		e proper jacking points, all jack heads must bear		
-		t be supported by firm and level surfaces		
-	-			
4) Ensure you are working on an even level surface, chock the wheels of the un-effected axle5) Apply the parking brake in conjunction with chocking the wheels.				
6) Lever lock on jack should be in the upright position				
7) Begin jacking the vehicle	in the upright position			
8) Lower lever lock on floor jac	k to the lowest positic	on, and lock in place		
9) Ensure both jack stands are	•	•		
10) Slowly lower the vehicle on	-			
11) Once the jack stands take up	•	stop lowering the jack		
12) Constantly be aware of surr				
engage the en	hergency stop and fol	is task, or there is an equipment malfunction, llow the lock out procedure DNS TO YOUR SUPERVISOR		
Guidance Documents/Stan MB Workplace Safety & Health Act	the	s Safe Work Procedure will be reviewed any time le task, equipment or materials change and at a minimum of every three years		
	-	iewed By WSH Committee:		
6 Personal Protective Equipment				
8 Musculoskeletal Injuries				
14 Fall Protection		e:		
16 Machines, Tools and Robots				
22 Powered Mobile Equipment				
28.37 Scaffolds and Other Elevated W	ork Platforms			