## Fueling Vehicle

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Eye injury	Steel toed boots	
Fire/Explosion hazards	Eye protection	
Burns	Hand protection	
	Safe Work Procedure:	
<ul> <li>3) Remove fill cap</li> <li>4) Insert nozzle in to tar</li> <li>5) Fill until click is heard</li> <li>6) Place nozzle back on</li> <li>7) Obtain receipt</li> </ul>	nguish any smoking material, leav hk and flip lever to on position l or to desired amount then turn l holder and replace the fill cap ccurs while conducting this task,	ever to off position or there is an equipment malfunction,
	ne emergency stop and follow the	
Guidance Doc	uments/Standards:	
MB Workplace Safety 6 Personal Protective Equipm 19 Fire and Explosive Hazards		This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three year
35 Workplace Hazardous Ma		Reviewed By WSH Committee:
		Date: