Acetylene

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Contents under pressure	Steel toed boots	
Inhalation	Face shield / safety glasses	
Spills	Safety glasses	
	leather gloves	
	Respirator	

Safe Work Procedure:

- 1) Use only in well ventilated areas
- 2) Do not wear contact lens when working with this chemical
- 3) Respirator selection must be based on the MSDS
- 4) Do not drag, roll or slide cylinders

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:	This Safe Work Procedure will be reviewed any	
	time the task, equipment or materials change	
MB Workplace Safety & Health Act & Regulations:	and at a minimum of every three years	
	Reviewed By WSH Committee:	
6 Personal Protective Equipment		
12.3 Hearing Protection		
16.4 Machine and Tool Safety	Date:	
19.10 Fire and Explosion Hazards		