Dyke Building

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Tripping	Hard Hat	Equipment Operator Training
Pinch points	Steel toed boots	
Moving equipment	Hearing protection	
Vehicle traffic		
Pedestrian traffic		

Safe Work Procedure:

- 1) Load and unload equipment when it get to work site
- 2) Load mud from pit area using excavator into rock trucks
- 3) Transport mud from pit to dyke building area and dump
- 4) Spread mud using dozers and regrade road/dyke
- 5) Place gravel on road using tracked crawler dumper and skid steer

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

task, equipment or materials change and at a	
minimum of every three years	
ved By WSH Committee:	
·	
•	